

LAND CORNER RECORD

Index: R-16	Corner: E1/16 between Sections 22 and 27			State of Indiana - Hoosier National Forest
Section: 27	Township: 7N	Range: 1E	P.M.: 2nd	County: Monroe
Coordinate:	Lat./N: 1374395.618	Long./E: 3149127.133	Datum: NAD83 IN West Zone, US Survey Feet	

CORNER HISTORY: (Chronological history of corner)


1.) Date of Survey:	Surveyor:	Monument:	Recording Information:		Monument Photograph:
4/29/1901	Lew Deckard Monroe County Surveyor	Stone set	Monroe County Surveyor's Office Bk. 2, Pg. 568		
Reference Objects:	Species:	Diameter:	Bearing:	Distance:	
Record evidence of prior survey:					
2.) Date of Survey:	Surveyor:	Monument:	Recording Information:		
5/14/1974	Andrew Sobiech L.S. #80040143	A 3"X4" stone with "+" on top found	USDA Forest Service Bedford, IN		
Reference Objects:	Species:	Diameter:	Bearing:	Distance:	
	Black Oak	6"	S60°W	12.10'	
	Black Oak	7"	S46°E	8.90'	
	White Oak	5"	N22°W	10.10'	
Record evidence of prior survey:					



ACCESSORIES: Bearing and distance from monument to witness object.

Reference Objects:	Object or Tree Species:	Diameter:	Bearing:	Distance:
	Black Oak** **	13"	S70°W	12.44'
	Twin Black Oak** **	12"	S40°E	8.39'
	White Oak**	13"	N02°E	17.58'
** = no paint * = old blaze at base of tree	Wood Post	4"x4"	S00°E	2.50'
Monument Found or Set:	A 3"x8" sandstone with a "+" on top was found 0.5' above grade.			


MONUMENT SKETCH



NARRATIVE REFERENCE:

Monument is a 3"x8" sandstone with a "+" on top, 0.5' above grade, a carsonite post is located 2.0' north of the monument, located further north on a ridge than the quad map indicated, on the western side of a north-south running ridge, +/- 50' west of the ridge top, +/- 200' east of a north-south running drainage at the bottom of the ridge, surrounded by mature forest.

SECTION DIAGRAM



Corner Location = ●

PERPETUATION RECORD:

The record monument was found undisturbed and maintained by remarking two existing bearing trees and establishing one new bearing tree. Two existing bearing trees were recovered from a Certified Land Corner Restoration by Andrew Sobiech, dated 5/14/1974.

One new bearing tree was marked with a blaze, scribed B.T., bearing tree sign and mag nail.

*Referenced on BRCJ survey recorded as InstNo.2018007752
Accepted by the Monroe County Surveyor Review Board on August 6, 2019.*

Section: 27 T7N R1E

Prepared By: BRCJ (Project#3-0822) Date: 5/2018

Index No. R-16
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 802-127T. 7N R. 1E 2nd Mer. N.F. Neosho County Monroe State Ind.
Corner common to sections 22, 27, and

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed _____	Year of search _____ By _____
Original monument _____ (Wood post, stone, pile of stones, pipe, etc.)	Monument found _____
Bearing Trees	Original Bearing Trees Found
Species _____	Species _____
Diameter _____	Diameter _____
Bearing _____	Bearing _____
Distance _____	Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____	Year of search <u>1974</u> By <u>N. Denton</u>
Where filed or recorded _____	<u>Found sandstone 3" square by 4" high</u>
Monument _____ (Original, concrete post, iron rod, etc.)	<u>marked w/ + on top. The stone lies in</u>
	<u>a fence line running N-S. It is</u>
	<u>19.45 ch. west of NE corner of Sec. 27</u>
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species _____	
Diameter _____	
Bearing _____	
Distance _____	



Sketch

○ Corner ■ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Found sandstone

3" square by 4" high marked w/ + in a fence

line running N-S. Stone is 19.45 ch. west of

NE corner of Sec. 27

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Survey

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No _____

5. Signature N. Denton

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Certified corner restoration certificate prepared:

Yes _____ No _____

Filed in county records at _____ Date _____

County Document No. _____

Identified on aerial photo No. _____

Which is filed at _____